


# Lake Orono Shoreline Restoration


## Liane McCullough

Shoreline  
Restoration



### Project Summary

The property located on Lake Orono has a steep slope leading to the lake and each year some of the shoreline slumps into the lake from wave action. Since her purchase of the property 12 years ago, Lee McCullough said they have lost 5 feet of shoreline. Curlex Bloc was installed along the shoreline with small plugs planted directly into the Curlex. Larger shrubs were planted upland to hold the remaining shoreline in place.



### Before installation - 2013/2014



Project Details	Project Funding	Project Partners
Date Installed ..... August 5th, 2014	2013 State Cost Share ..... \$1,000.00	Sherburne SWCD
Area ..... 400 ft <sup>2</sup>	Landowner ..... 1,037.97	Lee McCullough
Drainage Area ..... 8,000 ft <sup>2</sup>	Total Project Cost ..... \$2,037.97	
# of Shrubs ..... 39		
# of Plant Plugs ..... 102		



Completed - August 2014



Sherburne SWCD  
14855 Highway 10  
Elk River, MN 55330  
(763) 241-1170 ext. 4  
[www.sherburneswcd.org](http://www.sherburneswcd.org)

*The Sherburne County Soil & Water Conservation District is dedicated to working directly with landowners and agencies in order to promote the wise and sustainable use of our land and water related resources to educate and inform the public about these uses; to help solve the resource problems within the District and to serve as a county wide natural resource information and referral center.*

*Celebrating 70 years of conservation!*